

Vehicle Health Check Report



Parkway Northampton

Parkway Motor Group, Ferris Row, NN39HX, Tel: 01604321600

VHC Ref: 3405765H396VBD2152019 Service Advisor: David Laing Technician: Ryan Vale

Customer Name	Registration	Vehicle Description	Mileage	MOT Due D
Mr Smart	H396VBD	VOLKSWAGEN GOLF GL 4+E 1.8	44821	01/04/2

Address: 23 Delamere Road Northampton Telephone: 01604761396

Authorised Work	Warranty	Complete
Complete Alternator Belt/Battery	Battery failed test, requires replacing	No 22/05/201

Total price

Items OK	
Green	O/S Front Tyre 1.6 Outer: 4.0mm Middle: 4.0mm Inner: 4.0mm Goodyear 175/70/13 T 82
Green	N/S Front Tyre Outer: 4.0mm Middle: 4.0mm Inner: 4.0mm Goodyear 175/70/13 T 82
Green	O/S Rear Tyre Outer: 4.0mm Middle: 4.0mm Inner: 4.0mm Goodyear 175/70/13 T 82
Green	N/S Rear Tyre Outer: 4.0mm Middle: 4.0mm Inner: 4.0mm Goodyear 175/70/13 T 82
Green	Spare Space Saver Condition: Good
Green	Front Brakes N/S Pad Lining Not Visible, O/S Pad Lining Not Visible
Green	Hoses/Pipes/Cables Brake pipe on vehicle starting to rust
Green	Rear Brakes N/S Pad Lining Not Visible, O/S Pad Lining Not Visible
Green	Service Book Not required
Green	Service Indicator Not required
Green	Oil level Oil level ok
Green	Wheel Alignment
Green	Locking wheel nut
Green	Master Cylinder/Servo/Fluid
Green	Wheel Bearings
Green	Hand Brake Operation
Green	Wheel Trim
Green	Glass/Mirrors/Door Locks
Green	Brakes/Clutch/Transmission OP
Green	Engine Noise/Smoke
Green	Number Plate
Green	Cambelt Check
Green	Engine Oil Level
Green	Antifreeze Strength
Green	Water/Oil/Fluid Leaks
Green	Power Steering Fluid
Green	Brake Fluid Condition
Green	Fuel System
Green	Screenwash Strength
Green	Mandatory Lights Front (external)
Green	Mandatory Lights Rear (external)
Green	Mandatory Lights (interior)
Green	Horn/Wipers/Washers
Green	Air Con/Heating/Ventilation System
Green	Warning Lamps
Green	Seatbelts
Green	Exhaust System/Catalyst
Green	Steering
Green	Front Suspension
Green	Rear Suspension
Green	Driveshafts/Oil Leaks

Customer Signature(s):

Total Identified W